

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Kathleen Clarke **Executive Director** Lowell P. Braxton Bivision Director 801-359-3940 (Fax) 801-538-7223 (TDD)

1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801 801-538-5340

801-359-3940 (Fax)

INSPECTION REPORT

		4
	Exploration:	,
æ	and the second s	
	70:30 AM-12:15 PM	

Inspection Date & Time: Date of Last Inspection: 9/27/00

Permit Number: A

Partial: XXX Complete:

Min	e Name: Trail Mountain Mine County: Emery	Permit N	Number:	A	<u> </u>			
	nittee and/or Operator's Name: PacifiCorp							
Bus	iness Address: P.O. Box 310, Huntington, Utah 845	528						
Typ	e of Mining Activity: Underground XXX Surface	Prep.	Plant _	Other _				
Con	npany Official(s): Dennis Oakley							
	e Official(s): <u>Peter Hess</u> Federal Official(s): <u>None</u>							
	ather Conditions: Cool, 50's Fahrenheit/ Sunny							
Evid	sting Acreage: Permitted 4178 Disturbed 10.7	Regraded		Seeded				
Ctot	us: Exploration Active XXX Inactive	Tomporory Cos	esation	Rond Forfe	eiture			
Stat	Reclamation (Phase I Phase II Final Box	d Dologgo	Lighility	Vear)			
	Reciamation (Phase I Phase II Philai Boi	id Kelease	Liabilit	y 1 Can				
	REVIEW OF PERMIT, PERFORMANCE STANDARI	S & PERMIT CO	ONDITIC	N REQUIREME	NTS			
1.	Substantiate the elements on this inspection by checking the appropr	iate performance sta	andard.	ON REQUIREME	1112			
••	a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to							
	the site, in which case check N/A.		_					
	b. For <u>partial inspections</u> check only the elements evaluated.							
2.	Document any noncompliance situation by referencing the NOV issu	ied at the appropriat	te perform	ance standard listed	below.			
3.	Reference any narratives written in conjunction with this inspection	at the appropriate pe	erformanc	e standard listed bel	low.			
4.	Provide a brief status report for all pending enforcement actions, per	mit conditions, Divi	ision Orde	ers, and amendments	S.			
		EVALUATED	N/A	COMMENTS	NOV/ENF			
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	П						
	SIGNS AND MARKERS	<u>[X]</u>	\Box	\Box	$\overline{\Box}$			
	TOPSOIL	П	\Box	\Box				
	HYDROLOGIC BALANCE:	· 	_	_				
	a. DIVERSIONS	[X]	П	[X]	П			
	b. SEDIMENT PONDS AND IMPOUNDMENTS	<u> </u>		П	$\overline{\Box}$			
	c. OTHER SEDIMENT CONTROL MEASURES	<u>[X]</u>	$\overline{\Box}$	[X]	\Box			
	d. WATER MONITORING	[X]	П	[X]	\Box			
	e. EFFLUENT LIMITATIONS	П	П	\Box	\Box			
5.	EXPLOSIVES	[X]	\Box		\Box			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	Ш	[X]	П	\Box			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	\Box	\Box	П			
	NONCOAL WASTE	[X]	\Box	П	П			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	Ц	\Box	Ц	\Box			
	ENVIRONMENTAL ISSUES							
	SLIDES AND OTHER DAMAGE	Ц	[X]	П				
	CONTEMPORANEOUS RECLAMATION		[X]	\Box				
	BACKFILLING AND GRADING	Ц	[X]	\Box				
	REVEGETATION	\Box	[X]		П			
	SUBSIDENCE CONTROL	\Box	\Box	Ц	П			
	CESSATION OF OPERATIONS		\Box	Ц	П			
16.	ROADS:							
	a. CONSTRUCTION/MAINTENANCE/SURFACING	\Box	П	Ц	Ц			
	b. DRAINAGE CONTROLS	[X]	\Box	Ц	Ц			
	OTHER TRANSPORTATION FACILITIES	П		Ш	Ц			
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	П	П	П	Ц			
	AVS CHECK (4th Quarter- April, May, June)		Ц	Ц	П			
	AIR QUALITY PERMIT	. П	\Box	П	Ц			
21.	BONDING & INSURANCE	[]	\Box	П	\Box			

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 10/11/00

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4A. HYDROLOGIC BALANCE: DIVERSIONS

A shallow concrete ditch reports the collected inflow from the Mine site disturbed area to pond 001A. At the end of this ditch, a significant erosion feature was noted where the flow drops off the end of the concrete, thence into the pond. It also appears that, at some time, a flow jumped the shallow concrete ditch at a turn in the diversion and eroded soils from this area. Mr. Oakley agreed to repair both areas.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The Trail Mountain site has two alternate sediment control areas; the first is a fill slope on the North end of the parking lot area. Sediment control is provided via a silt fence and riprap on the slope. The second ASCA is South of pond 001A, and is immediately adjacent to the Emery County road. The treated flows from both areas report to Cottonwood Creek.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Due to a reason unknown to this inspector, it was necessary for the permittee to resubmit the discharge monitoring reports for the Trail Mountain Mine for the months of January, April and May, 2000. These reports were reviewed along with the June, July, and August, 2000 UPDES reporting forms.

The following was determined during today's review; the Trail Mountain Mine has two UPDES outfalls; of these, only 002A, which is the mine water discharge point, flows consistently. During the six months which were reviewed flows varied from 257,000 GPD to 535,000 GPD. UPDES outfall 002A did not have any UPDES parameter exceedances during the months which were reviewed. All reporting forms were submitted in a timely fashion.

Point 001A is the mine site sediment pond.

Inspector's Signature:

Peter Hess #46

Date: November 2, 2000

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

 $O: \label{lem:compliance} O: \label{lem:co$